
# RHIC vacuum limitations

## Wolfram Fischer

- 1. Pressure rise observations injection transition store
- 2. Pressure instabilities
- 3. Counter measures






	Au <sup>79+</sup>	$\mathbf{d}^+$	$\mathbf{p}^+$
Pressure rise locations	only warm		warm / cold
		Injection	
Pressure rise observed	Yes	Yes	Yes
E-clouds observed directly	Yes	Yes	Yes
	Transition		
Pressure rise observed	Yes	Yes	N/A
E-clouds observed directly	Yes with large losses	No	N/A
	Store		
Pressure rise observed	Yes	No	No no rebucketing
E-clouds observed directly	No	No	No

Pressure rise observed Yes = pressure rise ≥ 1 decade E-clouds observed directly = observed with electron detector

### Pressure rise mechanisms considered so far

- Electron cloud →dominating for operational problems
  - Coherent tune shift in bunch train
  - Electron detectors
- Ion desorption → tolerable for operation
  - Rest gas ionization, acceleration through beam
  - Ion energies ~15eV for Au, ~60eV for p
  - Visible pressure rise, may lead to instability in conjunction with electron clouds (Au only)
- Beam loss induced desorption →tolerable for operation
  - Need large beam loss for significant pressure rise
  - New desorption measurements in 2004
     (H. Huang, S.Y. Zhang, U. Iriso, and others)

**Electron cloud and pressure rise** 



### **U. Iriso-Ariz**


Clear connection between e-cloud and pressure at injection

Estimate for  $\eta_e$  assuming pressure caused by e-cloud: 0.001-0.02

(large error from multiple sources)

[U. Iriso-Ariz et al. "Electron cloud observations at RHIC in Run-3", BNL C-A/AP/129 (2003).]


Gas density increase observed in cold regions with intense proton beams




# Cold surface not very clean (acceptable so far):

- Pressure when cool-down starts: 1e-1 Torr (in almost all cold regions in the past)
  - → About 10 mono-layers after cool-down
- Pumping 500m arcs with turbo for 2 weeks: 1e-3 Torr (10 days after stop pumping: 1e-2 Torr)
- Need to install more turbo pumps
  - $\rightarrow$  1e-3 Torr initial pressure results in 0.1 mono-layer


## Typical transition pressure rise in Au-Au operation








Strongly intensity dependent



No correlation with beam loss


→ suggests electron clouds

Stronger pressure rise for fewer bunches in IR12 (independent of pattern in IR10 – same as Run-3, S.Y. Zhang)





→ Behavior can be qualitatively reproduced in e-cloud simulation (U. Iriso)

With fewer bunches, cloud density and current into wall is reduced, but <u>electron impact energy is increased</u>, and can lead to larger desorption. (simulation by U. Iriso)



PHOBOS background increase after rebucketing, drops after minutes to 2 hours (most severe luminosity limit in Run-4)






Did not find narrow range that triggers problem for

- average bunch intensity
- peak bunch intensity
- pressure before rebucketing

No good correlation with any parameter and duration either



Considered 2 cases:

#### At IP:

nominal bunch spacing (~216ns) and double intensity

## At end of the beryllium pipe:


normal intensity, spacing of 40ns then 176ns


[G. Rumolo and W. Fischer, "Observation on background in PHOBOS and related electron cloud simulations", BNL C-A/AP/146 (2004).]

## Important result:

After surface parameter calibration find e-clouds at end of 12m Be pipe, but not in center


→ May be sufficient to suppress e-cloud at ends





Center of Be pipe

End of Be pipe



Location of unbaked collimator (unbaked due to scheduling conflict)

- In a number of cases vacuum instabilities were observed (pressure grows exponentially without bound)
- Vacuum instabilities seen
  - Only with Au<sup>79+</sup> beam
  - Only at locations with unbaked surfaces
  - At injection (previous runs)
  - At store, after rebucketing (Run-4)
  - May be at transition
     (growth time large compared to transition crossing time)
- Growth times range from 2 to 12 sec

- Need feedback mechanisms for instability (gas load *Q* proportional to rest gas pressure P):
  - Rest gas ionization by cloud electrons

$$Q_2 = \sigma_e P \frac{2rL}{e} \frac{dI_e}{dl} \eta_{ion}$$

Rest gas ionization by beam

$$Q_3 = \sigma_b P L \dot{N}_b \eta_{ion}$$

Define parameter (analog ISR instability)

$$b = \sigma_e \frac{2r}{e} \frac{dI_e}{dl} + \sigma_b \dot{N}$$

e-cloud (20%) beam (80%) ionization

 Critical desorption coefficient for ionized and accelerated rest gas molecules

$$\eta_{crit,ion} = \frac{\pi^2}{4} \frac{c}{bL^2}$$

c – conducdanceL – half distancebetween pumps

Growth time (very approximate)

$$\tau = \frac{\pi r^2}{b}$$

r – pipe radius

Parameter	Unit	<b>Au</b> <sup>79+</sup>	$\mathbf{p}^{+}$
Reported η <sub>H2</sub> [CERN 99-	• • •	0.4	1.5
Reported $\eta_{CO}$ [CERN 99-	• • •	0.3	1.2
$\overset{05]}{\text{Calc.}} \eta_{\text{H 2 critical}}$	•••	42	131
Calc. $\eta_{CO\ critical}$	• • •	2.8	14
Meas. growth time τ	sec	6-12	
Calc. growth time $\tau_{H2}$	sec	23	
Calc. growth time $\tau_{CO}$	sec	5.4	

- e-clouds contribute about 20% of effect
- Instability may be possible for Au<sup>79+</sup> and CO like molecules.
- Still significant discrepancy between reported  $\eta$  and calc.  $\eta_{crit}$  (higher charge state rest gas ions important?)
- Note: No η measurements available for ion energies below 100 eV.

- In-situ baking of warm elements
  - (>85% of 700m/ring warm pipes baked)
  - → Occasionally installation schedules were too tight
- NEG coated pipes (low SEY, additional pumping)
  - → About 250m of NEG coated pipes installed
- Optimized bunch patterns
  - → Most uniform along circumference, used this year
- More pumping of before cool-down
  - → Need more turbo pumps for full coverage
- Solenoids, scrubbing
  - → Tested, no large scale implementation planned near term

• All operational relevant dynamic pressure rises in RHIC can be explained with electron clouds (abnormal large beam losses can still lead to unacceptable vacuum)

- Electron cloud driven pressure rises observed
  - With all species (Au<sup>79+</sup>, d<sup>+</sup>, p<sup>+</sup>)
  - In warm and cold regions
  - At injection, transition and store
- Pressure instabilities only for Au<sup>79+</sup> and unbaked wall (likely caused by rest gas ionization by beam and electron cloud)
- Current counter measures:
  - Complete baking of all elements
  - NEG coated warm beam pipes
  - Optimized bunch patterns
  - Probably pre-pumping of cold sections before cool-down